



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
directly across road from 11	RYLE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800 pit directly opposite 11 (same as felled tree)	434218.77	385005.3	Tilia americana 'Redmond'	434218.03	385005.25